

Enquiries: Nonkululeko Kgoshe

Tel: 018 397 3337

Email: NonkululekoM@sassa.gov.za

Ref. No. 6/2/R

ERRATUM: SASSA 51-21-CS-NW: APPOINTMENT OF A SERVICE PROVIDER(S) TO DEPLOY NETWORK INFRASTRUCTURE AND EQUIPMENT AT REGIONAL OFFICE NEW BUILDING.

 During the compulsory briefing session which was conducted at the new Regional Office Building next to Mega City, on Tuesday, 15 February at 11:00, the following errors were discovered and required rectification.

2. On the *Detailed Specifications and Requirements* on page 6 of 14 it was discovered that the name and model of the 20kVA UPS which requires installation of new batteries was not specified. The UPS information is as follows:


Name: APC


Model: MGE Galaxy 300

3. It was discovered that the floor plans for building were omitted as part of the specification document. The floor plans are attached for ease of reference.

Kind regards

Ms Motshidisi Mokoena General Manager Finance Date: 17 02 2022






Pa Mooren

2000/2416

return Genera Mannera. Conforme



AS AGREED, ABOVE FLOOR PLAN for PARTITIONING IS APPROVED TO AE PER MUTING HELD WEST DOSSIDATION

7. RD Mooden Herma General Mamacia Colorare Jerneer. SASSA. HIW.

Jul 6/0606